Conduct of Operations Course

Exercise:

Maintenance Activity Observation

Time Required: 60 minutes

Reference: (a) DOE-EM-STD-5505-96, Operations Assessments (Pgs. 6-8)

Activities: Using the exercise materials, the student will:

- 1. Practice the observation techniques discussed in the Operations Assessments Standard.
- 2. Identify the deficiencies which are observed during a video tape of a facility maintenance activity.

Objective: The above activities support student performance of the following:

1. Identify the key elements of assessments, surveillance, and audits, and their application (1.c)

Instructional Aids/Materials:

- 1. Television, VCR, and Maintenance Activity Video Tape.
- 2. Instructor Guide and Student Workbook
- 3. DOE-EM-STD-5505-96, Operations Assessments

Presentation Method: Video Tape, Class Discussion

Instructor Notes:

- 1. Refer to the Student Workbook. Students should be instructed to identify the deficiencies and to record them in the space provided.
- 2. The underlined words are key words that have been intentionally left blank in the student workbook.
- 3. The italicized words are for instructors only and do not appear in the student workbook.

Exercise: Maintenance Activity Observation

Instructions:

- a) Observe the video and identify the deficiencies.
- b) Record the deficiencies in the space provided.
- c) Discuss the deficiencies with the class.

SHOW THE VIDEO

DISCUSS THE DEFICIENCIES

Deficiency List:

Panel Maintenance

- 1. No briefing by the supervisor. Did not ensure adequate understanding. No review of documentation.
- 2. No supervisor check of qualification/level of knowledge "You've done this before, haven't you?"
- 3. Supervisor incorrectly stated procedure number as 5240. The wrong procedure was taken to the job site.
- 4. Technicians did not review procedure.
- 5. Technician made connections in live cabinet without electrical safety precautions.
- 6. Use of improper tools (wrong size screwdriver and slip-joint pliers) on instrument valve.

- 7. Job delayed due to inadequate prep (wrong pipe fitting).
- 8. Work performed across radiological barrier without gloves.
- 9. No action taken to correct potentially contaminated water on floor.
- 10. One technician took hard hat off.
- 11. Completed task with wrong procedure.
- 12. Trainee actions were unsupervised.
- 13. Work performed on wrong rack (H21-P005 instead of H21-P004).
- 14. Control room was not notified prior to start of work.

NOTES